





UFP-220 INSTALLATION INSTRUCTIONS

Adapter Plate (1) 	M4 x 5mm Phillips Head Screws (4ea) 	M4 x 10mm Phillips Head Screws (6ea) 
--	---	--

1. **Figure 1:** Attach the UFP-220 Adapter Plate to the back of the display using the six M4 x 10mm screws.

NOTE: Depending on the mount purchased, take the following steps to attach the mount.

2. **Figure 1A:** Attach the PRF mounting plate to the back of the UFP-220 using the M4 x 5mm screws.
3. **Figure 1B:** Attach the PTM/AM2 mounting plate to the back of the UFP-220 using the M4 x 5mm screws.
4. **Figure 1C:** Attach the SOAD mounting plate to the back of the UFP-220 using the M4 x 5mm screws.

CAUTION: DO NOT OVERTIGHTEN THE SCREWS.

Figure 1






Fig. 1A




PRF

Fig. 1B



PTM/ AM2

Fig. 1C



SOA